



18	1	Resistor	Stackpole Electronics	RMCF 1/16S 0 R
17	1	Resistor	Yageo	RC0402JR-07510RL
16	1	Resistor	Stackpole Electronics	RMCF 1/16S 4.7K 5% R
15	9	Resistor	Stackpole Electronics	RMCF 1/16S 10K 5% R
14	1	Resistor	Stackpole Electronics	RMCF 1/16S 1M 5% R
13	2	Ceramic Capacitor	Murata Electronics	GRM1555C1H180JZ01D
12	2	Ceramic Capacitor	Murata Electronics	GRM1555C1H470JZ01D
11	5	Ceramic Capacitor	Taiyo Yuden	EMK105BJ104KV-F
10	3	Ceramic Capacitor	TDK Corporation	C1005X5R1C334K
9	1	Diode	Comchip Technology	BAS70-G
8	1	Header	Sullins	PBC07DAAN
7	3	Socket	Samtec Inc.	QSH-030-01-L-D-A
6	1	LED	Avago Technologies	HSMY-C170
5	1	Tactile Switch	Omron	B3S-1002P
4	1	ZIF Socket	Enplas	FPQ-64-0.5-06
3	1	MCU Reset IC	STMicroelectronics	STM6315RDW13F
2	1	Crystal	NDK	NX5032GA-25.000000MHZ
1	1	PCB	Freescale Semi	CDC2215
ITEM	QTY	NAME	MATERIAL	DESCRIPTION

Parts List

FILE NAME	LFMAJ04EE2M.dwg
CONTRACT NO	-
DRAWN	09/01/2011 CJW
CHECK	
APPR.	
ISSUED	



NXP Semiconductors  
28125 Cabot Drive, Suite 100  
Novi, Michigan 48377

LQFP Debug Board  
MPC5604 64 Pin

NOTE: DIMENSIONS ARE IN MILLIMETERS DO NOT SCALE DRAWING	SIZE B	FSCM NO -	DWG NO LFMAJ04EE2M	REV
SCALE	1:1	WEIGHT	SHEET 1 of 2	